

EQ-9800 & 9850 Supported Densitometers

The following is a list of supported densitometers for calibrating the EQ-9800 and 9850 series printers:

- X-Rite DTP 32
- EFI Spectrometer ES-1000
- X-Rite DTP 41
- EFI Densitometer ED-100

To calibrate the printer, you will use the Fiery Command Workstation and/or the Colorwise tools to bring the Calibration tool up, select your densitometer, and then calibrate. The methods and steps will be slightly different from densitometer to densitometer.